




# ASBESTOS DISPOSAL

- Asbestos-Containing Material (ACM) can be present in:
  - Sprayed coatings
  - Pipe Insulation
  - Insulating boards
  - Ropes, yarns and cloth
  - Millboard, paper and paper products
  - Asbestos cement
  - Floor tile, mastics and sealants
- Friable and non-friable ACM generated on Fort Bragg are accepted for disposal in the C&D landfill
- All ACM must be packaged in accordance with 40 CFR 61:
  - Adequately wet
  - In leak-tight packaging
  - Properly labeled





# ASBESTOS DISPOSAL

## Landfill Notification

- Notify landfill 24 hours in advance at 910-396-6873 so an asbestos disposal area can be prepped
  - Leave a detailed, clearly enunciated message that contains a POC and phone number
  - Landfill personnel will return understandable messages and schedule appointments
  - Do not come to the landfill without an appointment
  - All ACM must be at the landfill before 1300 – loads arriving after this time will be rescheduled

# ASBESTOS DISPOSAL

## Friable Asbestos

- FRIABLE ASBESTOS: any material which contains more than 1 percent asbestos, and when dry, can be crumbled, pulverized or reduced to powder by hand pressure
- Examples of Friable ACM:
  - Acoustic ceiling tile
  - Wall jointing compound or "mud"
  - Thermal insulation for water heaters and pipes





# ASBESTOS DISPOSAL

## Friable Asbestos

- Bring valid **Landfill Usage Permit**
- Driver completes block 10 on a legible **NC Asbestos Waste Shipment Record** and gives to scale operator 
- Driver completes parts 1 and 2 on **Fort Bragg Asbestos Removal, Transportation and Disposal Documentation Form** and gives to scale house for recording inbound weight
- Obtain “FRIABLE ASBESTOS CONTAINING MATERIALS” sign from scale house operator and display in truck windshield 

**FRIABLE  
ASBESTOS CONTAINING MATERIALS**



# ASBESTOS DISPOSAL

## Friable Asbestos (continued)

- Proceed to appropriate disposal area as directed by scale operators
- Wait for direction of C&D operator to specific disposal area
- Unload ACM in a manner that ensures no release of ACM from bags
- Implement dust minimization measures
- After emptying load, proceed back to scale house



# ASBESTOS DISPOSAL

## Friable Asbestos (continued)


- Ensure scale house operator:
  - Records outbound weight
  - Signs, Dates, and Records ACM weight in Block 13 of **NC Asbestos Waste Shipment Record**
  - Signs Section 3 of the **Fort Bragg Asbestos Removal, Transportation and Disposal Documentation Form**
- Scale house retains three legible copies of the **NC Asbestos Waste Shipment Record** and returns remaining copies to the driver.
- Return the “FRIABLE ASBESTOS CONTAINING MATERIALS” sign to the scale house operator.

# ASBESTOS DISPOSAL

## Non-Friable Asbestos



- NON-FRIABLE ASBESTOS:
  - Any material containing more than 1 percent asbestos that when dry, cannot be crumbled, pulverized or reduced to powder by hand pressure
  - Contains a binder or hardening agent, such as cement, asphalt or vinyl, that helps prevent the ACM from becoming friable
- Examples of Non-Friable Asbestos:
  - Flexible building boards
  - Sealants
  - Vinyl floor tiles
  - Roofing materials





# ASBESTOS DISPOSAL

## Non-Friable Asbestos

- Bring valid Landfill Usage Permit.
- Complete parts 1 and 2 of **Fort Bragg Asbestos Removal, Transportation and Disposal Documentation Form**. Give to scale house operator to record inbound weight. 
- Display “NON-FRIABLE ASBESTOS CONTAINING MATERIALS” sign in truck windshield (scale house operators have these signs).

**NON-FRIABLE  
ASBESTOS CONTAINING MATERIALS**



# ASBESTOS DISPOSAL

## Non-Friable Asbestos (continued)

- Proceed to appropriate disposal area as directed by scale operators
- Wait for direction of C&D operator to specific disposal area
- Unload ACM in a manner that ensures no bags are ripped
- Implement dust minimization measures
- After emptying load, proceed back to scale house



# ASBESTOS DISPOSAL

## Non-Friable Asbestos (Continued)

- Ensure scale house operator records outbound weight and signs Section 3 of the **Fort Bragg Asbestos Removal, Transportation and Disposal Documentation Form**.
- Return the “NON-FRIABLE ASBESTOS CONTAINING MATERIALS” sign to scale house operators.

# Lamont Rd Landfill

## Asbestos Disposal



Area #6  
Concrete Recycling

Area #5  
Tree & Yard  
Waste Recycling

Area #4  
Concertina Wire

Area #3  
Pallets

Area #8  
Construction and  
Demolition Debris  
and Asbestos

*Proceed to asbestos  
area only as directed  
by landfill personnel*

Area #1  
Furniture  
Mattresses

Environmental  
Outpost

Aluminum

Scrap Metal

Area #2  
Recycling

Cardboard

Landfill Office

Scale House and Scales

Lamont Road

Area #7  
Transfer Station  
Household Waste

**Read all posted signs!**  
**Ask if not sure!**  
**Speed limit: 10 mph**  
**Hours: 0730-1500**